

Riverside Offices report

Generated 2 Oct 2026, 10:30

DETAILS

Technician	Daniel Foster
Client / location	Riverside Offices
Visit type	Planned maintenance

AIR CONDITIONER 1

Result	Everything in order
--------	---------------------



AIR CONDITIONER 2

Result	Everything in order
--------	---------------------



MAIN PUMP

Result	Issue found
Finding	Water leak at the hose-clamp connection.
Action	The corroded clamp was replaced and the connection checked.
Status on departure	Completed

BEFORE



AFTER



GENERAL COMMENT

The planned inspection was completed. Both air-conditioning units are operating normally. The corroded clamp on the main pump was replaced, and the leak did not return during the final check.